



COMMONWEALTH OF PENNSYLVANIA DEPARTMENT OF ENVIRONMENTAL RESOURCES

Post Office Box 2063 Harrisburg, Pennsylvania 17120

Bureau of Waste Management

Preliminary Assessment

FOR Domino Salvage Demolition Landfill PA #1823

> City of Plymouth Meeting Montgomery County Pennsylvania



PRELIMINARY ASSESSMENT NARRATIVE

DOMINO SALVAGE / GOLF BALL QUARRY

PA-1823

SEPTEMBER 1987

DIVISION OF ELIENGENCE & REMEDIAL RESPONSE

SEP - 9 1987

Waste Management



DOMINO SALVAGE INC. A.K.A. Golf Ball Quarry PA-1823

HISTORY

The quarry which hosts this disposal site has its origins in Revolutionary War times. Determining the origins of the common name for the quarry has proven both futile and irrelevant. To put the readers mind to rest, there is no evidence that George Washington ever played golf here — even though the quarry would have made a spectacular trap. The roads, Germantown Pike and Butler Pike, are among the oldest in the nation and probably followed Indian trails. It follows that natural resources found along such roadways would be the first to be exploited. This area has shallow and easily mined limestone formations and limestone quarries are common. That this quarry is among the oldest is evidenced by the protected remnants of two unrestored kilns adjacent to the site. These kilns, regarded as historical sites, have been spared the relentless development pressure of the suburban Philadelphia area, and preserve the national historical flavor of the region.

The DER historical record begins in 1974 when an application for a Demolition Waste Landfill was submitted in the name of Domino Salvage Inc. At that time the Edwin Leedom estate owned the property, and lease agreements were submitted with the permit application. The class III demolition waste application was received by DER on 9-27-74 and a permit, #100986, was issued on 12-6-74. It appeared that the operation got off to a shaky when a DER letter dated 1-27-75 chastised Mr. Sabia, owner of Domino Salvage, for reportedly accepting wastes other than those allowed by the permit. No subsequent events of this type were noted by the files during the brief operating history of the site.

The files end with a memorandum from a DER Geologist dated 4-14-78 which noted, "the currently permitted site, Plymouth Golf Ball Quarry, is no longer receiving demolition waste and final grading and covering activities have begun".

LOCATION

The Germantown and Butler Pikes intersection is approximately 4 miles southeast of Norristown and 3 miles northwest of Conshohocken in Plymouth Twp. Montgomery CO. This area is a rapidly growing suburb of Philadelphia. The Pa Turnpike is .08 miles north of the site and contributes much to the areas commercial attractiveness.



PRESENT CONDITIONS

The limestone quarry, commonly known as Plymouth Golf Ball Quarry, has been completely backfilled, graded, and developed into a commercial site. Five large structures, housing a variety of corporate and professional offices, presently occupy the approximately 4 acre site. The only remnants of the sites former conditions is a small impondment area on the northern perimeter of the site which is used as a catch basin for the paved parking lots. This impondment is used to reduce the rate of precipitation runoff to a small unnamed tributary of the Schuylkill River.

The impondment never totally drains and has given rise to some swamp type vegetation, notably Typha. The minimum water surface area is approximately 15'X40' and may double at peak level. The observed water quality is only slightly brackish because of stagnation. No trace of leachate or other condition which could be attributed to the demolition waste was observed.

The surface of the site is 70-80% under roof or paved, and the rest is well established vegetation. Therefore, infiltration is minimal and leachate outbreaks would be unlikely.

POTENTIAL HAZARDS

There were no known hazardous materials deposited at the site. The letter of 1-27-75 from George Buchanan to Mike Sabia did not specify what the "wastes other than demolition wastes" were. The limited information available did not indicate any further incidents. Given the highly visible nature of the site, in full view of two heavily traveled highways and only 1.25 miles from the DER Regional Office, violations of the permit is improbable.

Should unknown hazardous materials be present, two possible routes of contamination are possible. First, the fact that the waste was deposited in an abandoned limestone quarry, even with the deposition of a 6' soil liner, makes groundwater contamination a concern. There are 3 public water supply wells within 3 miles. All are owned by the Philadelphia Suburban Water Co. and receive regular analysis. The presence of this and other permitted and possible unpermitted disposal sites in the area are known to PSWCO. and DER's Bureau of Community Environmental Control. The second possible route of contamination is through the surface water via an unnamed tributary of the Schuylkill River. This tributary flows approximately 3-4 miles in a southwesterly direction and borders the City of Conshohocken. This stream is not part of a currently active stream sampling program, therefore information on the stream quality is unavailable.



RECOMMENDATION

This facility received approximately 125,000 cubic yards of demolition wastes. There is no evidence of hazardous wastes or municipal wastes being deposited, nor is there any indication of adverse environmental or public health impacts from this site. Because the site exhibits negligible potential for further problems, no further action under CERCLA is recommended and the site is being given a "low" rating on the Preliminary Assessment form.



POTENTIAL HAZARDOUS WASTE SITE

I. IDENTIFICATION				
01 STATE	02 SITE NUMBER			
PA	1823			

SEPA	PRELIMINA! PART 1 - SITE INFORM			l PA l	1823	
II. SITE NAME AND LOCATION						
1 SITE NAME (Legal, common, or descriptive name of site)		02 STREE	T, ROUTE NO., C	A SPECIFIC LOCATION IDENTIFIER		
Domino Salvage Demolition	Landfill	Gern	nantown 8	& Butler Pikes		
3 CITY			05 ZIP CODE		07COUNTY	
Plymouth Meeting		Pa	19462	Montgomery	CODE	DIST
GOORDINATES LATITUDE 40° 06' 14'' 7	16' 48"					
DIRECTIONS TO SITE (Starting from nearest public road)						
					_	
From exit 25 of the Pa tu	-				les.	
'Site is on the North quad	rant of the int	tersect	ion with	Butler Pike.		
I. RESPONSIBLE PARTIES		······································				• • • • • • • • • • • • • • • • • • • •
1 OWNER (# known)		02 STREE	T (Business, meding,	reaidential)	· · · · · · · · · · · · · · · · · · ·	
C.N. Leedom			30 Park	Λ ₃₇ ο		
SCITY LEEGON			05 ZIP CODE	108 TELEPHONE NUMBER	1	
· ·		1	19406	() N.A.		
King Of Prussia					<u></u>	
7 OPERATOR (If known and different from owner)		1	T (Business, meeting,			
Michael G. Sabia		1251	Conshor	nocken Road		
9 CITY		1_	11 ZIP CODE	12 TELEPHONE NUMBER		
Conshohocken		Pa.	19428	215, 275-1580	1	
OWNER/OPERATOR NOTIFICATION ON FILE (Check at a construction) A. RCRA 3001 DATE RECEIVED: MONTH DAY ON SITE INSPECTION YES DATE 07-16-87 NO MONTH DAY YEAR SITE STATUS (Check one) A. ACTIVE DB. INACTIVE C. UNKI	B. UNCONTRO Y YEAR AZARD BY (Check of that apply) A. EPA B. E. LOCAL HEALTH O CONTRACTOR NAME(S) 03 YEARS OF OP NOWN T. KNOWN, OR ALLEGED	EPA CONTRA FFICIAL (CTOR \$	C. STATE D. OTHER	R CONTRACTOR	. NONE
/I. INFORMATION AVAILABLE FROM	a checked, complete Part 2 · Waste I M XXC, LOW (Inspect on I	information and Pa	n: 3 - Description of H		setion form)	
DI CONTACT	02 OF (Agency/Org	lanization)			03 TELEPHONE	MUMBEH
Gary F. Shaffer 04 PERSON RESPONSIBLE FOR ASSESSMENT	Div of E	OB ORGA	INIZATION	ial Response 07 TELEPHONE NUMBER	717-621- 08 DATE	-3118
same	DER		au of e Mnot.	(717+787-7816	08	1 87 VENE



POTENTIAL HAZARDOUS WASTE SITE

L	I. IDENTIFICATION			
ſ	01 STATE PA	02 SITE NUMBER 1823		

				ASSESSMENT EINFORMATION		PA 1823	NUMBER
II. WASTE ST	ATES, QUANTITIES, AN	ID CHARACTERI	STICS				
01 PHYSICAL STATES (Check as that apply) Waste Quanti (Measures o must be T B. POWDER, FINES F. LIQUID TONS		TY AT SITE I waste quantities independent)	☐ 8. CORROSIVE ☐ F. INFECTIOUS ☐ J. EXPL		BLE II I. HIGHLY TIOUS II J. EXPLOS MABLE II K. REACTI	SIVE IVE	
	iSøecily)	NO. OF DRUMS _					
III. WASTE T	YPE						
CATEGORY	SUBSTANCE N	AME	01 GROSS AMOUNT	02 UNIT OF MEASURE	03 COMMENTS		
SLU	SLUDGE		NA				
оџу	OILY WASTE		NA				
SOL	SOLVENTS		NA				
PSD	PESTICIDES		NA				
occ	OTHER ORGANIC CH	HEMICALS	NA				
IOC	INORGANIC CHEMIC	ALS	NI A				
ACD	ACIDS		NA				
BAS	BASES		NA-				
MES	HEAVY METALS		1111				
IV. HAZARDO	OUS SUBSTANCES (See A)	ppendix for most frequent	ty caed CAS Numbers)				
01 CATEGORY	02 SUBSTANCE N	AME	03 CAS NUMBER	04 STORAGE/DISF	POSAL METHOD	05 CONCENTRATION	06 MEASURE OF CONCENTRATION
	NA						
	***************************************		<u> </u>				
				<u> </u>			
	····		 				
							
				<u> </u>			
	······································		ļ	ļ			
		···-					
				1			
V. FEEDSTO	CKS (See Appendix for CAS Numb	ers)					
CATEGORY	01 FEEDSTOC	K NAME	02 CAS NUMBER	CATEGORY	01 FEEDSTO	OCK NAME	02 CAS NUMBER
FDS	NA			FDS			
FDS				FDS			
FDS				FDS			
FDS			FDS				
			<u> </u>				
DER Fil Michael	DER Files Michael Sabia Wayne Lynn - DER employee						



POTENTIAL HAZARDOUS WASTE SITE

1. IDENTIFICATION 01 STATE 02 SITE NUMBER

	MINARY ASSESSMENT HAZARDOUS CONDITIONS AND INCID	ENTS PA	1823
IL HAZARDOUS CONDITIONS AND INCIDENTS	TIAZARDOGG CONDITIONS AND INGID		
01 © A. GROUNDWATER CONTAMINATION 03 POPULATION POTENTIALLY AFFECTED: 60,000+	02 C OBSERVED (DATE:) 💯 POTENTIAL	□ ALLEGED
01 © B. SURFACE WATER CONTAMINATION 03 POPULATION POTENTIALLY AFFECTED: unknown	02 © OBSERVED (DATE:) XI POTENTIAL	□ ALLEGED
01 C. CONTAMINATION OF AIR 03 POPULATION POTENTIALLY AFFECTED: none suspected	02 C OBSERVED (DATE:04 NARRATIVE DESCRIPTION) POTENTIAL	□ ALLEGED
01 □ D. FIRE-EXPLOSIVE CONDITIONS 03 POPULATION POTENTIALLY AFFECTED:	02 C OBSERVED (DATE:04 NARRATIVE DESCRIPTION) POTENTIAL	□ ALLEGED
O1 C E. DIRECT CONTACT O3 POPULATION POTENTIALLY AFFECTED: none suspected	02 TOBSERVED (DATE:04 NARRATIVE DESCRIPTION) DOTENTIAL	□ ALLEGED
01 G F. CONTAMINATION OF SOIL 03 AREA POTENTIALLY AFFECTED: (Acres)	02 G OBSERVED (DATE:04 NARRATIVE DESCRIPTION) $\chi^{\!$	□ ALLEGED
01 T. G. DRINKING WATER CONTAMINATION 03 POPULATION POTENTIALLY AFFECTED: <u>unknown</u>	02 C OBSERVED (DATE04 NARRATIVE DESCRIPTION) G _X POTENTIAL	C ALLEGED
01 TH. WORKER EXPOSURE/INJURY 03 WORKERS POTENTIALLY AFFECTED:	02 TOBSERVED (DATE:04 NARRATIVE DESCRIPTION) DOTENTIAL	□ ALLEGED
none suspected 01 C I. POPULATION EXPOSURE/INJURY 03 POPULATION POTENTIALLY AFFECTED:	02 C OBSERVED (DATE:) POTENTIAL	□ ALLEGED
none suspected			



L IDENTIFICATION **POTENTIAL HAZARDOUS WASTE SITE** 01 STATE 02 SITE NUMBER PRELIMINARY ASSESSMENT PA 1823 PART 3 - DESCRIPTION OF HAZARDOUS CONDITIONS AND INCIDENTS II. HAZARDOUS CONDITIONS AND INCIDENTS (Continued) 01 J. DAMAGE TO FLORA ☐ POTENTIAL 02 G OBSERVED (DATE: ______) □ ALLEGED 04 NARRATIVE DESCRIPTION none suspected 01 DK. DAMAGE TO FAUNA 02 OBSERVED (DATE: _____) ☐ POTENTIAL ☐ ALLEGED 04 NARRATIVE DESCRIPTION (Include name(s) of species) none suspected 01 E L CONTAMINATION OF FOOD CHAIN 02 GBSERVED (DATE: ______) ☐ POTENTIAL ☐ ALLEGED 04 NARRATIVE DESCRIPTION none suspected

	01 M. UNSTABLE CONTAINMENT OF WASTES (Spatial runoff standing injuris/leaking drums) 03 POPULATION POTENTIALLY AFFECTED:	02 □ OBSERVED (DATE:) 04 NARRATIVE DESCRIPTION	□ POTENTIAL	□ ALLEGED
	none suspected			
	01 DN. DAMAGE TO OFFSITE PROPERTY 04 NARRATIVE DESCRIPTION	02 G OBSERVED (DATE:)	☐ POTENTIAL	☐ ALLEGED
	none suspected			
_	01 O. CONTAMINATION OF SEWERS, STORM DRAINS, WWTPs	02 G OBSERVED (DATE:)	☐ POTENTIAL	☐ ALLEGED

none			
)1 ☐ P. ILLEGAL/UNAUTHORIZED DUMPING 04 NARRATIVE DESCRIPTION	02 □ OBSERVED (DATE:)	POTENTIAL	☐ ALLEGED
none			

05 DESCRIPTION OF ANY OTHER KNOWN, POTENTIAL, OR ALLEGED HAZARDS

none known

04 NARRATIVE DESCRIPTION

60,000 area pop. III. TOTAL POPULATION POTENTIALLY AFFECTED: IV. COMMENTS

see attached narrative

V. SOURCES OF INFORMATION (Cre specific references, e.g., state files, sample analysis, reports)

DER files

Mike Sabia

onsite inspection

Wayne Lynn - DER employee

FIELD TRIP SUMMARY REPORT

This summary should be prepared in conjunction with the Preliminary Assessment, Form 2070-12.

OPIGUE.

EPA	Case	Number
ביום	Case	Mamper

PA-1823

Site Name Domino Salvage Demolition Landfill

Site Description

Site is 4 acres in area and is a fully developed commercial office complex of 5 structures. Site was formerly a limestone quarry. In 1974 6 feet of soil was placed and the site was filled with 125,000 yd³ of classIII demolition waste.

Area of site (acres) four

Hazardous portion, if not entire site

none

Description of processes/operations which took place at the site

Landfill disposal operation including daily, intermediate and final cover. Disposal of demolition waste only.

No precessing onsite.

Waste handling/disposal practices

Waste was dumped directly into the working face area by truck, compacted by heavy equipment, and covered with soil.

Site topography and runoff drainage pathways

Runoff is to an unnamed tributary of the Schuylkill River. Drainage is to the North.

Surface or subsurface drainage areas (leachate) noted?

Odors/stains not-d?

no

Stressed vegetation noted?

Location and description of streams or receiving waters adjacent to site. Include flow direction and observations. Note location on attached map.

Storm water drainage to an unnamed tributary of Schuylkill River. Flow is to the Southwest.

Monitoring wells on site or in vicinity. Note location on attached map.

- no onsite monitoring wells

Population within ¼ mile of site:	Population within 1 mile of site: ORIGINAL ROOT
□ 0-10	□ 0-10
☐ 10 - 100	□ 10-100
☐ greater than 100	☐ 100-1000 ∰ greater than 1000
	XX greater than 1000
Surrounding land use (woodlot, agricultura	1, recreation, industrial etc.)
NORTH	EAST
Residential/commercial	Residential
SOUTH Residential	WEST Residential / commercial
	s (note use of surface water and/or wells)
yes - 3 wells owned by Philadelphis Subur	ban water Co.
Reference:	
Domestic wells. Approximate number within	ik mile: 0
List nearest wells below and show location	
Owner/Resident Add	lress Phone
Groundwater flow direction, if known	
unknown	
Description of odor/taste problems	
unknown	
<u> </u>	
State inspection activity (including permi	its held)
Demolition waste Disposal Permit # 100986	
	•
State/Federal/Private remedial activities	
none	

Additional	commentsFurther	description	of	cita
Additional	commentsrurtner	description	ΟL	Site

See attached Narrative

SITE CONTACTS		
Name and Title	Affiliation	Phone
Michael G. Sabia	former operator	215-275-1580
Wayne Lynn	DER Manager	215-270-1948

INSPECTION INFORMATION					
Name and title of inspector(s) Gary F. Shaffer Project Officer					
Agency Div of Emergency & Remedial Response Phone number 717-621-3118					
Date07-16-87	Time on site2.5 hrs				
Weather conditions: Hot, Sunny, calm wind					

ATTACHMENTS

- o Topographic map identifying site location. Include name of quadrangle map.
- o Site sketch map showing location of monitoring wells, domestic wells, municipal water supplies, and areas of concern (lagoons, leachate seeps, drums, etc.)
- o Any available sampling results or state monitoring data with map showing sample locations.

NORRISTOWN QUADRANGLE TO THE NORRISTOWN **PENNSYLVANIA** 7.5 MINUTE SERIES (TOPOGRAPHIC) ALLENTOWN 37 MI. INTERCHANGE 31 (PA. 63) 10 MI. | 2 690 000 FEET 75°15' 477 17'30" 40°07'30" WHITPAIN250 INTERCHANGE 5 ž Hickorytown Sunnybrook Country Club 4440 Cold Point Oplymouth SITE LOCATION 290 000 FEET ORadio Towers ounding Spring Mill Andorre Sprime 4436

